

MagnumUSA.com

MATERIAL SAFETY DATA SHEET

DATE PREPARED: 2010

Section I – PRODUCT IDENTIFICATION AND EMERGENCY INFORMATION

Material Name: Exothermic Cutting Rods/tubes

Manufacturer: Magnum Mfg. Inc. dba MagnumUSA.

8979 Lager Road

Phelan CA 92371

Emergency Telephone Number: (800) 957-4344/760-868-6748

Facsimile: (760) 868-6749

Section II – HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

There are no hazardous materials contained in or used in the manufacture of exothermic cutting rods/tubes.

Section III – PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point	N/A	Specific Gravity (H2O=1)	N/A
Vapor Pressure (mm Hg)	N/A	Melting Point	N/A
Vapor Density (Air=1)	N/A	Evaporation Rate	N/A
		(Butyl Acetate=1)	
Solubility in Water	Insoluble in water		
Appearance and Odor	- Copper coated steel tube filled with wires. No odor.		

Section IV – FIRE AND EXPLOSION HAZARD DATA

Flammability -	N	o
Flammability Conditions -	N/A	
Means of Extinction -	N/A	
Special Fire Fighting Procedures -	N/A	
Unusual Fire and Explosion Hazards -	N/A	
Precautions to be taken in handling and storing -	N/A	
Flashpoint -	N	/A
Explosion limits -	N/A	
Auto-ignition Temperature -	N/A	
Hazardous Combustion Products -	See Section V	
Sensitivity to Mechanical Impact -	N/A	
Sensitivity to Static Discharge -	N/A	

Section V – REACTIVITY DATA

Stability - Stable material

Conditions to Avoid - None

Materials to Avoid - Combustibles (sparks are generated when rod is lit)

Hazardous Decomposition/Byproducts - Fumes generated during cutting may contain a variety of hazardous components. Know the target material.

Section VI – TOXICOLOGICAL PROPERTIES

Route of Entry:

Skin Contact -	N	/A	UV	Exposure -	YES
Eye Contact -		N/A		Inhalation Acute -	YES
Inhalation Chronic -		N/A	I	Ingestion -	N /A

Effects of acute exposure to material – Products of combustion include fumes and gases containing iron oxide and copper oxide as well as oxides of the material being cut. Fumes can aggravate asthma or bronchial conditions. Arc rays can burn eyes and skin. Cutting flame produces intense heat and can burn skin and ignite clothing.

Effects of chronic exposure to material – Not known.

Carcinogenicity – Not known.

Section VII - PREVENTATIVE MEASURES

Personal Protective Equipment:

Gloves -	Welders gloves/Flameproof.
Eyes -	Protective face shield with No. 5 or No. 6 lens.
Respiratory -	Use only in well ventilated areas. Provide adequate exhaust to assure clean air within the breathing zone. Keep head out of fumes. When cutting materials whose oxides are potentially toxic, use special breathing apparatus.
Other -	Wear protective clothing and shoes. See ANSI Z-49.1 “Safety in Welding and Cutting”.
Engineering Controls -	Use with adequate ventilation
Leak and Spill Procedures -	N/A
Waste Disposal -	Scrap metal can be recycled or land filled as local regulations allow.
Handling procedures and equipment -	N/A
Storage requirements -	Store in low humidity environment. Keep packaging material until ready to use.
Special shipping information -	N/A

Section VIII - FIRST AID MEASURES

Remove injured person from work area to fresh air. If skin is burned apply burn ointment and consult a physician. If eyes are burned consult a physician. If respiratory difficulty persists, seek medical attention. Wash face and hands after use.